

Statement of Analytical Results - Final

Job 119959

Camp Chikopi

Bob Duenkel
373 CHIKOPI RD, MAGNETAWAN ON P0A 1P0

**260042250 - CAMP CHIKOPI (WASHROOM) WATER
TREATMENT PLANT**

Lab ID 19G2212
Collection Date 2019-Jul-30
Collection Time 08:30
Matrix Distribution
Description 7 Hop

Criteria Reg 170
Sampler C Duenkel
Received 2019 Jul 30 16:20

Criteria
SDWA /
Ont. Reg.
170/03

	MDL / RDL	Units	Method	Completed	Analyst
Lead, total	0.0011	-	-	0.01	0.0001 mg/L ICP/MS 2019-Aug-13 -

MDL denotes Method Detection Limit, and expresses the lowest concentration that can be detected for the analysis

[R] Indicates Reported Detection Limit (RDL) used in place of an MDL

* Sample diluted prior to analysis

¹ Indicates an accredited test by Near North Laboratories Inc. to CALA to ISO/IEC 17025. ² Indicates analyses were subcontracted to an accredited laboratory.

Preparation: All samples were processed in accordance to the recommendations of "Standard Methods for the Examination of Water and Wastewater", AWWA, 23rd Ed. and Ontario Ministry of the Environment, Conservation and Parks protocols.

QC report available upon request. Sample(s) received in good condition, unless otherwise noted.

Near North Laboratories Inc. does not accept liability for the collection/handling of samples; nor representation and custody of samples prior to submission to the laboratory; the only exception to this statement is for samples collected/handled/in custody of NNL staff from the time of sampling. It is agreed that if Near North Laboratories Inc. should be found liable for any losses or damages attributable to the services provided, the liability shall be limited to and not exceed the amount of the fee paid by the Client for the services; this limit of liability may constitute the re-test / re-provision of the service or a refund of the fee paid.


 2019 Aug 16
 Renée Roy, Quality Manager

